#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-004813

Address: 333 Burma Road **Date Inspected:** 21-Nov-2008

City: Oakland, CA 94607

**OSM Arrival Time:** 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes **Huang Weng Pang** No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A Yes N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG** and **SAS** Tower Fabrication

#### **Summary of Items Observed:**

Bay 4: Tower Diaphragm

This QA observed ZPMC/NDE perform MT on the following weld joints of tower diaphragm with Aaron Wintrich. This QA and Aaron Wintrich also performed MT on weld joints mentioned below.

- a)ESD1-SA404-1A, 1B deemed acceptable
- b)ESD1-SA381A/B-1A,1B deemed acceptable
- c)ESD1-SA381A/B-13~18 deemed acceptable
- d)ESD1-SA381B/B-1, 2, 7 &8 deemed acceptable
- e)ESD1-SA404-4 deemed acceptable
- f)ESD1-SA424A/B-9A, 9B, 10A, 10B deemed acceptable
- g)ESD1-SA425-3A, 3B, 4A, 4B deemed acceptable
- h)ESD1-SA381A/B-4 deemed acceptable

## Bay 7: OBG - Floor Beam Sub Assembly

This QA observed ZPMC/personnel gouged/carbon arc of two transverse linear indications on fillet weld of flange to web plate connection of floor beam FB012-007-001 per critical weld report B-CWR 190. After completing carbon arc and grinding, this QA again observed ZPMC/NDE Wang Wei perform MT on the removal of transverse linear indications. This QA also perform MT on the linear indications removal and found acceptable.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)





# **Summary of Conversations:**

No significant conversation ocurred today.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Joshua Ishibashi, (858) 232-7091, who represents the Office of Structural Materials for your project.

<b>Inspected By:</b>	Lizardo, Joselito	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer